ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	**Ward No.**	**Ward Name**
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0546	3rd Main Rd	Beteehalli Lyt Bus Stop
Segment No.	**Total Length (m)**	
3/S-W0546/S012240	203.74	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	203.74	77.557478	13.092612	77.559347	13.092420	Beteehalli Lyt Bus Stop	Raja Kaluve

Work Details

History of Road / Lane / Circles	**Sanctioned Estimated Amount (Rs.)**	**Sanctioned Year**
Name of the Work	4240000	2014
Improvements to Veerasagara Main Road and Drain Construction of Samudaya at Doddabeteehalli village Ward No.03 of Yelahanka Satellite Town.		
	Type of Work	**Other Work Type**
Year	Drain Maintenance	
2014 - 2015	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Veerasagara Main Road and Drain Construction of Samudaya at Doddabeteehalli village Ward No 03 of Yelahanka Satellite Town.	003-14-000046
Not a Tender	**Work Order Date**	**Period of Extention**
	06/02/2014	90 Days
Work Order No.		**Multiple road involved with the same Job No/ Work Code #**
BBMP/EE/(YNK.D)/W.O/460/2013 -14	**Defect Liability Period To**	No
Defect Liability Period From	06/02/2016	
06/02/2014		

Contractor Details

Name of Contractor	**Contractor Reg No (BBMP/PWD)**	**Expenditure Booked \ Released (Rs)**
Technical Manager West KRIDL		28601102.17
Phone No.	**E-Mail ID**	
9449863065		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

Field Inspection Details

Number of Trees	Any Other Information	Name
0		pradeep
Date of Inspection	**Remarks**	
21/12/2015	comp	

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

R N Pradeep

40

eld Inspection Details

Number of Trees	Any Other Information	Name
1		pradeep
Date of Inspection	**Remarks**	
21/12/2015	comp	

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Segment End		Location was not determined.
Segment Start		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark

ಸಹಾಯಕ ಕಾರ್ಯ ಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಬಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

B.N Pradeep

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0546

Date: 21/12/2015 Time: 14:02:25 RH20151221140225